

Release Note KX-TGP500/550 Firmware

Version History

12.10

- **Additions:**
 1. The specification which can select always opening WEB port by configuration file.
(Added parameter : HTTPD_PORTOPEN_AUTO)
 2. The automatic reboot setting after the success of pre-provisioning with DHCP server option 66 can be set up by configuration file.
(Added parameter : OPTION66_REBOOT)
 3. The specification which can select adding the "Contact" header to SIP ACK message by configuration file.
(Added parameter : SIP_CONTACT_ON_ACK_[1-8])
 4. The specification which can change the volume of outband DTMF tone by configuration file and changed the default value from 0dB to -5dB.
(Added parameter : OUTBANDDTMF_VOL)

- **Corrections:**
 1. Improved that the voice could not be heard for a few seconds when configuration file was downloaded.

12.06

- **Additions:**
 1. Multi Number Settings can be set up by configuration file.
Added the following to configuration file.
INCOMING_CALL_GROUP_[1-8]
OUTGOING_CALL_LINE_HS[1-6]
OUTGOING_CALL_LINE_BS
DEFAULT_LINE_SELECT_HS[1-6]
DEFAULT_LINE_SELECT_BS

- **Corrections:**
 1. Improved the display of New Voicemail on TGP550 Base unit.
 2. Improved that the SIP parameter containing a capital letter could not be recognized.

12.04

- **Additions:**

1. Added the specification of supporting the letters in sip line id for registering SIP server.
(LINE_ID is added to Configuration file and WEB settings.)
 2. Disclosed the specification of checking the username part of the SIP URI in the "To" header when receiving the INVITE message with an incorrect target SIP URI
(SIP_RCV_DET_HEADER is added to Configuration, and the default setting of SIP_RCV_DET_HEADER is changed to N from Y.)
- **Corrections:**
 1. Improved handset telephone call sound.
 2. Improved all erase operation of the CID when the group setting of receiving call was changed from the default.

12.02

- **First Release Version**